HANGZHOU REEVOO INDUSTRY CO., LTD
NO.159-4 FENGPU RD., FUYANG DISTRICT, HANGZHOU CITY, ZHEJIANG PROVINCE, CHINA.

The following sample(s) was/were submitted and identified on behalf of the client as:

Sample Description	: PVC TARPAULIN
SGS Ref No.	: SDHL1711023086FB
Style / Item No.	: RV-HW2-610 (1020)
Client Reference Information	: 610G/SQ.M BASE FABRIC:1000DX1000D 20X20
P.O. / Ref. No.	: (2017RV2104)
Manufacture	: HANGZHOU REEVOO INDUSTRY CO., LTD
Supplier	: HANGZHOU REEVOO INDUSTRY CO., LTD
Sample Receiving Date	: Nov. 01, 2017
Test Performing Date	: Nov. 01, 2017 to Nov. 07, 2017
Test Performed	: Selected test(s) as requested by applicant
Test Result(s)	: For further details, please refer to the following page(s)

Test Result Summary

No.	Test(s) Requested	Result(s)	Comments
1	NFPA 701 Test Method 1-2015 Edition: Standard Methods of Fire Tests for Flame Propagation of Textiles and Films	PASS	/
For further details, please refer to the following page(s)			

Signed for and on behalf of
Xiamen Branch, SGS-CSTC Co., Ltd.

Sharky Xia
Approved Signatory

SGS-CSTC Standards Technical Services Co., Ltd. Xiamen Branch Testing Center Hardlines

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn
中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编: 361101 t (86-592) 5766537 f (86-592) 5766460 e sgs.china@sgs.com

Test Conducted:

NFPA 701 Test Method 1-2015 Edition: Standard Methods of Fire Tests for Flame Propagation of Textiles and Films

General Information:

Materials:	PVC Fabric	Weight	680 g/m^2
Conditioning	Dry at (105±3)℃, Duration: 30min		

Criteria for test method 1 (Chapter 10):

1. Fragments or residues of specimens that fall to the floor of the test chamber shall not continue to burn for more than an average of 2 seconds per specimen for the sample of 10 specimen.
2. The average weight loss of the 10 specimen in a sample shall be 40 percent or less.
3. No individual specimen's percent mass loss shall deviate more than 3 standard deviations from the mean for the 10 specimens.
4. When a retest is required, no individual specimen's percent mass loss in the second set of specimens shall deviate from the mean value by more than 3 standard deviations calculated for the second set.

Test Results:

Specimen	Original Mass (g)	Post Mass (g)	Residues (seconds)	Mass Loss (percent)
1	43.1	42.8	0.0	0.7
2	43.4	42.8	0.0	1.4
3	43.2	42.5	0.0	1.6
4	42.9	42.4	0.0	1.2
5	42.0	41.7	0.0	0.7
6	43.1	42.5	0.0	1.4
7	42.7	42.2	0.0	1.2
8	42.8	42.1	0.0	1.6
9	43.2	42.5	0.0	1.6
10	43.3	42.7	0.0	1.4
		AVG	0.0	1.3
		3*STDEV	---	1.0
		AVG+3STDEV	---	2.3

Conclusion: **PASS.** The submitted sample complied with the performance requirement of test method 1 of NFPA 701.

Remark : This test was subcontracted to Shunde Branch, SGS-CSTC Co., Ltd.

SGS-CSTC Standards Technical Services Co., Ltd. Xiamen Branch Testing Center Hardlines


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn

中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编: 361101 t (86-592) 5766537 f (86-592) 5766460 e sgs.china@sgs.com

Sample Photo(s):



The testing report/certificate only refers to the sample(s) tested.

End of Report

SGS-CSTC Standards Technical Services Co., Ltd. Xiamen Branch Testing Center Hardlines

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn

中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编: 361101 t (86-592) 5766537 f (86-592) 5766460 e sgs.china@sgs.com